

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
ID
37-SILC1.1
IC-

Florida Mountain Mining Sites, Tip Top Mine
Silver City Vicinity
Owyhee County
Idaho

HAER No.ID-31-C

Brent Smith, Photographer June 21, 22, 23, 29, 1995

- | | |
|-----------|--|
| ID-31-C-1 | TIP TOP MINE. WEST SIDE OF STRUCTURE. CAMERA POINTED EAST. |
| ID-31-C-2 | TIP TOP MINE. NORTH AND EAST SIDE OF HOUSE. CAMERA POINTED SOUTH. |
| ID-31-C-3 | TIP TOP MINE. SOUTH SIDE OF HOUSE. CAMERA POINTED NORTH-NORTHWEST. |
| ID-31-C-4 | TIP TOP MINE. VIEW FROM WASTE ROCK ABOVE WITH WOOD REMAINS OF POSSIBLE ADIT IN LOWER LEFT. CAMERA POINTED WEST. |
| ID-31-C-5 | TIP TOP MINE. EAST SIDE OF STRUCTURE WITH COLLAPSED ADIT. CAMERA POINTED WEST. |
| ID-31-C-6 | TIP TOP MINE. DETAIL OF SIDING. SOUTHWEST CORNER OF STRUCTURE. CAMERA POINTED NORTHEAST. |
| ID-31-C-7 | TIP TOP MINE. DETAIL OF RAIL TRACKS LEADING INTO HOUSE TOWARDS COLLAPSED REAR OF BUILDING. DOOR HINGES VISIBLE AND CEILING SUPPORT IN ID-31-C-10 VISIBLE. |
| ID-31-C-8 | TIP TOP MINE. INTERIOR OF LIVING QUARTERS WITH FLOOR COVERING MATERIAL, AND PAINTED WALLS. CAMERA IS POINTED EAST-NORTHEAST. 2 X 4 FRAMING FOR TABLE OF BED IS VISIBLE ON FLOOR AND LEANING AGAINST WALL. ON LEFT SIDE IS AREA WHERE DETAIL OF TONGUE AND GROOVE IN PHOTO ID-31-C-11 WAS MADE. PHOTOGRAPH IS OF EAST/NORTH WALL WITH ADJOINING ORE ROOM/RAILS TO THE LEFT THROUGH OPENING VISIBLE IN ID-31-C-11. |
| ID-31-C-9 | TIP TOP MINE. INTERIOR VIEW OF LIVING QUARTER WITH STOVE PIPE AND DRAIN SETUP VISIBLE. CAMERA IS POINTED WEST. |

Florida Mountain Mining Sites, Tip Top Mine
HAER NO. ID-31-C (Page 2)
Index to Photographs

- ID-31-C-10 TIP TOP MINE. INTERIOR VIEW OF LIVING QUARTERS WITH CLOSET/HANGER AND VIEW INTO ORE ROOM. RAIL IS VISIBLE JUST THROUGH DOOR WAY. CAMERA POINTED NORTH-NORTHWEST.
- ID-31-C-11 TIP TOP MINE. DETAIL OF TONGUE AND GROOVE INTERIOR SIDING IN LIVING QUARTERS. CAMERA POINTED EAST.
- ID-31-C-12 TIP TOP MINE. WOODEN STRUCTURE ASSOCIATED WITH CABLES IN ID-31-C-13 AND ID-31-C-14 LOCATED ON SLOPE JUST BELOW TIP TOP HOUSE. CAMERA IS POINTED NORTH-NORTHWEST.
- ID-31-C-13 TIP TOP MINE. WOODEN STRUCTURE VISIBLE IN ID-31-C-12 IS IN UPPER LEFT. ALSO VISIBLE ARE TWO VERTICALLY BURIED LOGS ASSOCIATED WITH CABLES, ONE OF WHICH IS VISIBLE IN LOWER RIGHT. CAMERA POINTED SOUTH.
- ID-31-C-14 TIP TOP MINE. TAILINGS LOCATED DIRECTLY WEST FROM TIP TOP HOUSE. ID-31-C-12 WOODEN STRUCTURE IS VISIBLE IN TOP LEFT. CABLES VISIBLE LEFT AND CENTER OF TAILINGS. HOUSE IS JUST OVER APEX OF TAILINGS. CAMERA POINTED EAST.